



STEP 3

PLACE THE CROSSBAR ALING WITH THE BACK LEGS HOLES AS SHOWN IN FIGURE "C" PLACE THE SCREWS AND THE WASHERS AND TIGHTEN THE SCREWS INTO THE LEGS





STEP 4

FINALLY GET THE DESK UP RIGHT AND PLACE IT IN THE DESIRED LOCATION

UNION SCREW 1/4 X 3/4"

NOTE: REMEMBER THAT ALL THE SCREWS ARE AND AT THE END THAT ALL THE SCREWS HAVE BEEN IN THEIR POSITION WE ADJUST.

		DESCRIPTION	#
		BUTTON SOCKET SCREW 5/16 X 1-3/4"	4
ΓΛ	ASSEMBLING	LOCK WASHER 5/16	8
ifd	INSTRUCTIONS	FLAT WASHER 5/16 X 1"	4
		UNION SCREW 1/4 X 3/4"	4
INTERNATIONAL	I-DSK-E017	ALLEN KEY 3/16	1

ITEM	DESCRIPTION	#
	TORNILLO ALLEN 5/16 X 1-3/4"	4
1RON011	Rondana de presion 5/16	4
1RON003	RONDANA PLANA 5/16 X 1"	4
1TOR038	TORNILLO UNION 1/4 X 3/4" (19 MM) (ORO VIEJO)	4
1HER251	LLAVE ALLEN 5/32	1

